Subject: there is nothing on the woofer at all...
Posted by Andy G on Thu, 24 Jan 2002 20:04:01 GMT
View Forum Message <> Reply to Message

.... would putting a coil on the woofer possibly elleviate the problem?