Subject: Re: imaginary dip/measurement artifact
Posted by Adam on Wed, 27 Feb 2002 22:24:26 GMT
View Forum Message <> Reply to Message

I just noticed the two woofer discussion. You could try an MTM design, with a woofer above and below the horn.Adam