Subject: Re: C5 & R3 values - accuracy of driver
Posted by dbeardsl on Fri, 15 Mar 2002 14:49:35 GMT
View Forum Message <> Reply to Message

Hmm.. thats really odd that the inductance is off, try measuring a known inductance to make sure yer meter isn't funny. Thats mainly a function of voice coil winds and diameter, don't how that could change much from unit to unit... I'll let Wayne tackle the "She needs a 15.62uF cap, She needs it not, She needs a 16.52uF Cap, shee needs it not" problem