Subject: Re: Amp clipping
Posted by Wayne Parham on Thu, 11 Jul 2002 15:52:37 GMT
View Forum Message <> Reply to Message

That's weird. I see from the link you sent that the Jensen speaker has voice coil resistance of around 6 ohms and inductance of around 0.5 millihenry. That is pretty normal for a speaker like this, and similar to that of the Eminence Alpha 8.What's the condition of the voice coil on the Alpha 8? Are they new?