Subject: Maybe
Posted by LuxmanLover on Wed, 09 Oct 2002 00:43:55 GMT
View Forum Message <> Reply to Message

What you need to start the inductor is a dowel of Xdia. that is usually some weird non standard size. It needs to be exact length, parallel and all within thousands of an inch to work out right ...a bit beyond my means.Kelly