Subject: Re: Still more Theater 4 tweaking...
Posted by Neo on Wed, 16 Oct 2002 17:34:38 GMT
View Forum Message <> Reply to Message

Hi Garland,  Is it the tweeter coil you changed?  It must be because the woofer coil is 1mH.  I upgraded all my crossover components, except the tweeter coil.  Hmmmm... and that makes a difference?  It's not directly in the signal path... I wonder why ?  If you found a positive difference, I'll give it a try.Thanks for the info...Tom - (remember me... we talked at the meeting at DRCope's place.  I brought my rebuilt Pi 4 crossovers.)