Subject: if the woofer is
Posted by Sam P. on Sat, 12 Apr 2003 11:47:11 GMT
View Forum Message <> Reply to Message

at the lower end of the manufactures sensitivity spec, and the other driver/HORN combo is at the upper end of the nominal sensitivity, an unexpected difference exceeding 2dB could easily be encountered. Sometimes you just need to make adjustments, but his setup should be awesome regarding bass. I wonder how much of the difference is due to dispersion issues related to the round horns on axis response vs. a 90x40 one. Sam