Subject: Re: Altec 511B Ringing Update
Posted by Larry Moore on Tue, 13 May 2003 17:10:29 GMT
View Forum Message <> Reply to Message

FWIW, when I had 511Bs, cutting the webs out completely and in particular that little vertical spacer right in fron of where the driver mounts made as much, and probably more difference than "gapping the webs."