Subject: Help on making driver measurements, please?
Posted by wunhuanglo on Sun, 29 Jun 2003 21:03:45 GMT
View Forum Message <> Reply to Message

I want to be able to measure "Fs" (resonance) and Qts for drivers under various conditions; horn loaded, reflex loaded, free air, etc...I have to accomodate a number of restrictions:1. I'm an idiot2. I'm relatively poor3. I'm an idiot.I:1. have a PC2. can buy decent soundcard3. have a BK DVMCan anyone suggest how I might equip myself to make these measurements?TIA