Subject: Re: Help on measurements, Thanks Bill
Posted by JS on Thu, 03 Jul 2003 10:40:08 GMT
View Forum Message <> Reply to Message

I don't think you have to use the test jig - you just need good connections, as noted. The test jig is just a way of making things a bit easier / neater.Are you measuring a resistor around 8 ohms? The program will have problems measuring values that are too far away from the reference resistor, iirc.