Subject: Re: Subwoofer project update
Posted by hulkss on Wed, 31 Mar 2004 01:08:44 GMT
View Forum Message <> Reply to Message

I don't see a problem with the smaller vent. It's quit generous in size as it is now. By the way, many of the LABsub cabinets are very close to the back of the driver and obstruct this vent to a significant degree. If you change the magnet size there may be fitment/mounting screw access problems.