Subject: Re: Subwoofer project update
Posted by hulkss on Thu, 01 Apr 2004 00:45:27 GMT
View Forum Message <> Reply to Message

Tool up = Cost up = Price up.Chuffing sound may be an issue in a dipole bass speaker or in an application where the speaker is mounted backside out. Does Eminence believe that a .75" magnet vent could ever be audible or cause distortion in a closed back front horn cabinet?