Subject: Re: drop in replacements?
Posted by James W. Johnson on Thu, 29 Jul 2004 13:19:20 GMT
View Forum Message <> Reply to Message

Wayne,So are the following CTS drivers basically the same.. 1038,1041,1056 ?Are there any other drop in replacements for the One and Two Pis?