Subject: Follow up questions (help Wayne -anyone?)
Posted by ImTweaked on Wed, 25 May 2005 12:02:57 GMT
View Forum Message <> Reply to Message

I noticed that on one side of my speaker there is a parallel pair of resistors (looks to be red-red-black-gold). This is the parallel resitors mentioned in above post.This resistors pair is wired from the woofer +ve to the negative. Is this correct? I am missing these resistors on the other speaker. which is correct?Basically I do not have a schematic of pi2 crossover with me and noticed the difference while changing to the new Vifa tweeterTIA