Subject: Re: How to measure capacitance?
Posted by Bill Epstein on Mon, 26 May 2008 11:14:04 GMT
View Forum Message <> Reply to Message

I get a reading of .093nF very briefly, then back to zero, over the 9' of the cables but that can't be right. What's the right way to measure?