Subject: Re: Goodmans Axiom 201
Posted by Wayne Parham on Fri, 30 Jun 2006 16:06:26 GMT
View Forum Message <> Reply to Message

If you cannot obtain the data, you can measure the drivers using the procedure shown in the post called "T/S Measurements".