Subject: Re: Larger Driver
Posted by Zene Gillette on Mon, 04 Sep 2006 04:11:37 GMT
View Forum Message <> Reply to Message

Wayne ... It's not the terminals it's the leads that connect direcly to the vc. Explaination was they don't have strain relief so they vibrate until they break. Eminence is aware of problem so is not minor. Can send you one if it's of any importance. Might not be if you've had no problems. Zene