Subject: You've got mail!
Posted by Wayne Parham on Tue, 06 Mar 2007 18:38:27 GMT
View Forum Message <> Reply to Message

You've over-estimated the sensitivity of the tweeter horn.  I suggest the 14dB compensation circuit, which you'll see in the charts on the crossover document.