Subject: Re: Pro 4
Posted by Wayne Parham on Fri, 21 Dec 2007 22:58:46 GMT
View Forum Message <> Reply to Message

The driver and horn displace 120 cubic inches.  Cabinet tuning is fairly immune to small changes, so you'll be OK.  To get a feel for how much a change will affect response, modify port size or some other parameter in one of the box modeling programs and see how much effect there is.