Subject: Pi 12 v2
Posted by Roland Gama on Mon, 28 Jan 2008 09:26:23 GMT
View Forum Message <> Reply to Message

Hello Wayne,Started work on the above mentioned project. Began by drawing the motor chamber layout on the side panels.However I have trouble with two points on the plans which are not shown. The points where 1) MC9 and MC10 meet and 2) MC12 and MC11 meet.Could you clarify them for me.Or should I build the motor chamber first and let it fall to place?Awaiting help: Roland.