Subject: I couldn't help myself
Posted by Bill Epstein on Sat, 19 Jul 2008 11:23:21 GMT
View Forum Message <> Reply to Message

Just pulled the 6.8uF cap from the horn circuit and replaced it with an Obbligto metal film 'n oil I had on hand.A pair of the same @22uF are sitting on the bench looking at me....