Subject: Re: 8 pi plans
Posted by Wayne Parham on Tue, 02 Feb 2010 05:19:27 GMT
View Forum Message <> Reply to Message

You've got mail!

The problem with mounting the cornerhorn off the ground is the midhorn and tweeter would be unnaturally high. It was designed to be placed on the ground, but except for the height of the HF drivers, you could lift the cabinets, especially if you were using multiple bass sound sources. Maybe invert the cabinet, hanging the midhorn and tweeter below the bass bin.