Subject: Re: Pioneer RT-909
Posted by AudioAJ on Thu, 18 Feb 2010 19:27:00 GMT
View Forum Message <> Reply to Message

timestar wrote on Fri, 08 January 2010 15:01It was the belt...I just put a new one on.

For me, whenever I've had problems with speed issues, that's usually the first place I check. Go with the easiest and cheapest fixes first.