Subject: Re: One more time
Posted by Wayne Parham on Tue, 16 Nov 2010 09:31:19 GMT
View Forum Message <> Reply to Message

check internal standing wave modes. One of the most common problems I see with tower configurations is internal standing waves lining up in an unfavorable way and causing response anomalies. When you make a tower, the positions of woofer and port become somewhat critical. This is true for any large speaker with a midwoofer used through the midrange, but even more so with towers. There's more potential for unwanted standing wave problems. See the posts at the link below.
Internal Standing Waves