Subject: Re: How to measure T-S Parameters
Posted by Bill Epstein on Fri, 31 Dec 2010 20:52:38 GMT
View Forum Message <> Reply to Message

It looks to me that WT2 will measure the T&S parameters and import them to a box design program? Seems worthwhile on that basis.