Subject: Re: [Pi2 Tower] Insulation on braces
Posted by Wayne Parham on Mon, 03 Jan 2011 13:41:10 GMT
View Forum Message <> Reply to Message

The insulation on the braces should span the cross-section left to right and front to back, sort of like making "compartments" inside the speaker. The sound has to pass through the insulation to get to the port. It blocks midrange but bass passes right through. Like this: