Subject: Re: [Pi2 Tower] Insulation on braces
Posted by Wayne Parham on Thu, 06 Jan 2011 15:55:04 GMT
View Forum Message <> Reply to Message

You're right, only two sets of braces are required, one 1/3rd the way from the top (just under the midwoofer) and the other 1/3rd the way up from the bottom. They should have insulation sitting on them, spanning the cross-section.

That photo was one of Shane's builds, and he put in an extra brace. That's OK, but not required. The reason I posted this photo was to show how the insulation siting on top of the braces spans the cross-section of the cabinet.