Subject: Re: crossover board assembly
Posted by Wayne Parham on Mon, 29 Aug 2011 23:02:17 GMT
View Forum Message <> Reply to Message

No trick to it at all. Just trim the component leads to fit and solder them on. The photo below shows me drawing an outline on some gasket material, and it also shows a crossover in enough detail for you to see what I mean: