Subject: Curcuit breaker going off on Yamaha RX-385
Posted by chris on Sat, 18 Jun 2005 21:32:45 GMT
View Forum Message <> Reply to Message

The curcuit breaker has begun switching the unit off at even moderate volumes on my Yamaha rx-385 100wpc x 4 receiver. Any insight which will assist my rectifying this malfunction is eagerly sought and shall be amply appreciated. Thanks.