Subject: Re: 3 PI build
Posted by Wayne Parham on Mon, 17 Feb 2014 22:52:19 GMT
View Forum Message <> Reply to Message

There is a write-up about measuring T/S parameters in the link below:
T/S MeasurementsOf course, now days, with some of the automated measurement devices, you can literally get these specs with just a few clicks of the mouse and a test box or some weights (like coins taped on the cone). But the process and the formula that show what's going on "under the hood" are in that post, which may prove interesting.

Here's another post with useful T/S formula:
Measurement equipment and softwareAnd two posts that show formula for Helmholtz (bass-reflex box) resonance, and how it is manifested in the impedance curve:
Frequencies of Interest
Measure impedance