Subject: Re: Johnny5's four Pi build
Posted by johnnycamp5 on Wed, 29 Jul 2015 22:26:34 GMT
View Forum Message <> Reply to Message

Hello all.

I'm wondering why I see so many 4pi builds with insulation installed on the bottom panel?

With the 4pi plans that Wayne sent me, under the "General construction tips", it states very clearly-

"Use R11 or R13 insulation, covering the interior top, side nearest the port and the rear".

It also says to hang a piece of insulation on the brace.

Therefore, there should be no insulation on-

1- the side opposite the port
2- The back side of the front baffle
3- The bottom.

Wayne sent me the plans about three weeks ago.
Have the 4pi's been revised?