Subject: Re: CD Players That Skip
Posted by Kingfish on Sat, 07 Oct 2017 17:41:56 GMT
View Forum Message <> Reply to Message

gofar99 wrote on Wed, 04 October 2017 17:23 The less costly the player the more likely it will have a small buffer. Any made more than about 5 years ago will be more prone to this happening as memory was more costly back then.

That makes a lot of sense, thank you. Mine was a factory installed unit in a 4 year old car. I have a new CD this was happening to, but I'm not noticing any scratch marks yet.