Subject: Re: Counterpoint SA 1000
Posted by Manualblock on Fri, 31 Dec 2004 16:13:23 GMT
View Forum Message <> Reply to Message

The Dynaco's do that with bad filter and coupling caps. My 2c from experience. The Lytics also in the power supply.