Subject: Re: Why?
Posted by Manualblock on Wed, 26 Jan 2005 14:48:05 GMT
View Forum Message <> Reply to Message

Thanks for the Link AK; So in the parafeed you need to replace an expensive transformer with an expensive large choke; and in PP the mis-match unbalanced DC causes frequency imbalance; requireing much higher HT and therefor larger transformer.. Is that correct?Thanks J.R.