Subject: actually...
Posted by hurdy_gurdyman on Thu, 08 Sep 2005 12:38:10 GMT
View Forum Message <> Reply to Message

Pin 8 was hooked to pin 1, but with all the experimenting going on, it was un-hooked when the cathode resistors were installed.