Subject: Re: 4 Pi Build in San Luis Obispo - Parts Arrived, Got a Router Jig
Posted by alexg on Fri, 26 Mar 2021 18:47:38 GMT
View Forum Message <> Reply to Message

Wayne,

Thanks for the quick response. I am glad that I am not the only person that struggles to get stuff done.

For the subs, if I position ports on the bottom of the subs (facing down to the floor) is there a minimum distance that I should maintain between the bottom of the subs and the floor?

As far as dampening the horn, you had me at "I personally don't find it useful." ha! ha! If the designer doesn't think it is necessary then that is all that I need to know.