Subject: Re: PI 4 Upgrades
Posted by Wayne Parham on Thu, 22 Apr 2021 20:15:52 GMT
View Forum Message <> Reply to Message

No, they're not. You'll have to drill the H290C. When I had the mold made for the H290C, I wanted the extra thickness near the throat for strength, so I chose to omit the inner three mounting holes. The two-hole arrangement works for the B&C, Eminence and TAD drivers, as well as many others. But sadly, that makes the 2426 a little more work.