Subject: Thanks for the suggestions!
Posted by Wayne Parham on Mon, 19 Dec 2005 14:46:23 GMT
View Forum Message <> Reply to Message

fine. What may be more of a concern is physical, getting a part that will fit. It's a tight squeeze in there. I haven't had time to open it up and check the space available, but I remember that it's tight. I also remember it's going to be a pain in the ear to replace and I'll probably have to pull the PCB which means pulling loose every tube connection and basically rebuilding the whole amp. So it's probably gonna be a month or two before I can get around to it. But that scratchy knob really gets on my nerves...
Stoetkit construction manual