Subject: Re: 8 years later
Posted by Wayne Parham on Thu, 27 Jan 2022 16:11:54 GMT
View Forum Message <> Reply to Message

I'll be honest, I expected to see IN+ to 2+ as open if there's no sound. The fact that it shows continuity makes me think you should hear the midhorn. But another thing that could kill output would be a short across C4. You might measure across that component and report back.