Subject: Re: 4Pi - alternate compression driver mounting?
Posted by Wayne Parham on Mon, 31 Jan 2022 21:00:00 GMT
View Forum Message <> Reply to Message

I would strongly suggest adding insulation first. Especially the cross-section sheet. Try it straight. Try it diagonal. Make sure you can mitigate that peak at 120Hz.

I say this because you might find that your efforts to damp the peak are illusive, and you might end up moving the port. This is best learned while you're still in the "cut and try" mode.