Subject: Retubing the Cayin
Posted by colinhester on Thu, 06 Apr 2006 18:43:04 GMT
View Forum Message <> Reply to Message

Well, after swapping out the stock Chinese EL34s for the Svetlana Wing-Cs (thanks to BOI) I got the bug to put new tubes in the amp's front section and CDP. The amp is getting Mazda chrome plates (platinum grade) in the 12AX7 and 12AU7 sockets. The ShengYa CDP is getting a NOS Ediswan CV2492/6922. I don't know if the new tubes will "tickle my balls," as one reviewer recently told me about his mods, but there's always hope.....Colin
http://www.upscaleaudio.com/view_category.asp?cat=38