Subject: Re: New Production Tung Sol 6550, Penta KT88s
Posted by gofar99 on Tue, 24 Jan 2023 02:25:27 GMT
View Forum Message <> Reply to Message

Hi, something I would not have guessed. I agree that really small changes in components can make a difference. 0.1db of the wrong stuff in the wrong place can really mess up a good design. The saving grace if you want to call it that is the speaker and if you use a turntable the cartridge errors are far worse and will mask a lot of ones internal to the electronics.