I always mount the crossover board on the bottom of the cabinet too. Certainly always on the three Pi and four Pi models. I make the boards kinda weird, in that I mount the components on the solder side, which then leaves the other side flat. Then I mount the board on a gasket, directly on the cabinet panel rather than using stand-offs.