Subject: Re: PS Transformers
Posted by Manualblock on Sat, 29 Jul 2006 11:59:54 GMT
View Forum Message <> Reply to Message

Sorry; I assumed you were using the rated spec of the transformer and wall voltage. To measure off-load voltage you connect the primaries to the AC line input then use a voltmeter on the two legs of the secondaries right? But if you measure the voltages then why do you need the turns ratio? Thats already given by the primary and secondary voltage measurements.