Subject: Re: New Transformer
Posted by Manualblock on Mon, 07 Aug 2006 13:01:22 GMT
View Forum Message <> Reply to Message

I had a problem with that voltage also; and the trans weighs about 5 lbs.But this comes out of a Lafayette reciever so it may have used a voltage doubler. Here's a better description. The primary side has 7 tabs.Looking from left to right they are marked E 6V 2.3A(This one is connected across the trans to the other secondary) 6v.6a tab.117v/100v/0v Tabs 4&5&6The last tab is blank; no writing.On the sec side;6 tabs; starting from left to right;6.3v 2.7a Tab 1&26v .6A tab 3 and 4130V DC .16A tabs 5&6