Subject: mac 60
Posted by RS on Wed, 13 Jul 2005 15:36:43 GMT
View Forum Message <> Reply to Message

? if the coupling caps(2eax3 35,15,80,mf@500v)? are not all the same vaule ie replaceing a 44 for 35, 22 for 15 cause a bias mis match over time,sounds good for about 2hr then starts to loose output and distort.  fyi,hammond now has chokes for the mac60 #159t 2.5H@300mADC.

Subject: Re: mac 60
Posted by RS on Thu, 14 Jul 2005 13:59:09 GMT
View Forum Message <> Reply to Message

yes it dose matter,$20.of new caps and wala.ran for 5hrs so far with no problems.