Subject: Guinever done
Posted by Forty2wo on Tue, 01 Mar 2005 00:24:09 GMT
View Forum Message <> Reply to Message

Under going finel inspection by Jazz, chief wire tangler and all around big help...John
http://img209.exs.cx/img209/8776/gov9tq.jpg

Subject: Re: Guinever done
Posted by Manualblock on Tue, 01 Mar 2005 00:46:20 GMT
View Forum Message <> Reply to Message

John; Nice work; why are there two 5687's? And which rec tube did you use?

Subject: Many congrats
Posted by colinhester on Tue, 01 Mar 2005 01:10:47 GMT
View Forum Message <> Reply to Message

That's awesome. Looks like you beat me by a day. So, if that a high dielectric teflon coated cake pan?.....Colin

Subject: Nice....
Posted by PakProtector on Tue, 01 Mar 2005 01:48:16 GMT
View Forum Message <> Reply to Message

Love the cake-pan. Same questions, why two 5687 and what rectifier? did you perhaps parallel the two sections together?How does it sound? like you expected? better? comparable to the regulated version you heard in MD?regards,Douglas