
Subject: Re: Heat sink, Heat exchange for driver/cabinet
Posted by [Wayne Parham](#) on Mon, 06 Nov 2023 14:34:45 GMT
[View Forum Message](#) <> [Reply to Message](#)

The JBL 2226 is not machined to accept a cooling plug.
