

---

Subject: Re: Scott 299C and 7591 tubes  
Posted by [real\\_one](#) on Mon, 19 Nov 2007 15:20:40 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Check to make sure you didn't blow a capacitor. If so, replace it. If not, enjoy!

---