

---

Subject: Re: Scott 299C and 7591 tubes

Posted by [Forty2wo](#) on Mon, 19 Nov 2007 22:30:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The crackle and pop may just be dirty sockets. The act of removing and replacing the tubes cleans them to a degree. If you plan to use it on a regular basis I would consider replacing the electrolytic caps and maybe upgrading the bias supply...John

---